

Your logo
here

Your company name
address
Contact info

Report Id : 10083

Four Wheeler Report

Date:29-04-2021 13:25:02

Inspection Address : urban estate 2

Company Name	DEMO CASE	Parts	Description	Parts	Description
Branch Office	KHARAR 1	Front Bumper	Safe	Grill	Safe
Insurance Company Ref No	U34	Head Lamp (LT)	Safe	Head Lamp (RT)	Safe
Requester Name	Harpreet	Indicator Light (LT)	Safe	Indicator Light (RT)	Safe
Customer Name	Harpreet Singh	Fog Lamp (LT)	Safe	Fog Lamp (RT)	Safe
Customer Address	urban estate 2	Front Panel	Safe	Bonnet	Safe
Customer Contact Number	123456789	Left Apron	Safe	Right Apron	Safe
Vehicle Number	pb10p0757	LT Front Fender	Safe	LT Front Door	Safe
Chassis Number	833844383338	LT Rear Door	Safe	LT Pillar Door (A)	Safe
Engine Number	448434834348	LT Pillar Center (B)	Safe	LT Pillar Rear (C)	Safe
Odo Meter	35000 KMS	LT Running Board	Safe	LT Qtr Panel	Safe
RC Verified	Yes	Dicky	Safe	Rear Bumper	Safe
Vehicle Manufacturer	MARUTI	Tail Lamp (LT)	Safe	Tail Lamp (RT)	Safe
Year of Manufacture	2020	RT Qtr Panel	Safe	RT Rear Door	Safe
Vehicle Variant	LXI Wagon R	RT Front Door	Safe	RT Pillar Front (A)	Safe
Fuel Used	PETROL	RT Center Pillar (B)	Safe	RT Pillar Rear (C)	Safe
Vehicle Colour	white	RT Running Board	Safe	RT Front Fender	Safe
Engine Started	Yes	Floor / Silencer	Safe	Under Carriage	Safe
Inspection Status : Recommended		Rear View Mirror (LT)	Safe	Rear View Mirror (RT)	Safe
Remarks		Rim	Safe	Stereo / Make	Safe
OK		CD Changer / Make	Safe	Seat Cover	Safe
		Center Lock	Safe	Gear Locking	Safe
		Front w/s Glass	Safe	Left Front Door Glass	Safe
		Left Rear Door Glass	Safe	Back Glass	Safe
		Tyres	NA	Right Front Door Glass	Safe
		Right Rear Door Glass	Safe	Sun Roof Glass	Safe

Owner Declaration :
I/We hereby confirm that the vehicle has been inspected in presence of me/my/our representative.
I/We hereby confirm that the identification details and damages of vehicle as noted/photographs taken by the inspecting officer are correct. Nothing has been hidden/undisclosed.
I/We agreed that Repair/Replacement of dented/crack parts & Repair Painting of dented/scratched panels as per this inspection photographs shall be excluded in event of any claim lodged during the policy period.
I here certify that I have shown the same vehicle which I have to get insured and if later at the time of claim it is found that vehicle shown and accidental are different then no claim is payable to me.
I here certify that I will not claim for damages existing in my vehicle whether same are mentioned in report or not if same are seen in photograph taken by the inspector.

Executed by : m1
QC Done by : webrosoft



Customer Signature

00.8645110, 75.8398309
Date: 29-04-2021 Time: 13:25:06